





REVISIONS				
ZONE	REV	DESCRIPTION	DATE	APPROVED



Actual

Alloy 6063-T5 Metal: .062" typ. All corners .015" R Est. Wt. .255 #/ft. PPI 6.88 in. Industry Standard tolerances	Brunner Enterprises™ Inc			
	455 Center Road, West Seneca, NY 14224 (877) 299-2622 toll-free (716) 712-0183 fax www.brunnerent.com			
	SIZE	FSCM NO.	DWG NO.	REV
			D1105	
	SCALE 4:1		SHEET	


REVISIONS				
ZONE	REV	DESCRIPTION	DATE	APPROVED



Actual

Alloy 6063-T5 Metal: .062" typ. All corners .015" R Est. Wt. .184 #/ft. PPI 4.57 in. Industry Standard tolerances	Brunner Enterprises™ Inc			
	455 Center Road, West Seneca, NY 14224 (877) 299-2622 toll-free (716) 712-0183 fax www.brunnerent.com			
	SIZE	FSCM NO.	DWG NO.	REV
			D1108	
	SCALE 4:1		SHEET	

REVISIONS				
ZONE	REV	DESCRIPTION	DATE	APPROVED



Actual

Alloy 6063-T5 Metal: .062" typ. All corners .015" R Est. Wt. .165 #/ft. PPI 4.45 in. Industry Standard tolerances	Brunner Enterprises™ Inc			
	455 Center Road, West Seneca, NY 14224 (877) 299-2622 toll-free (716) 712-0183 fax www.brunnerent.com			
	SIZE	FSCM NO.	DWG NO.	REV
			D2052	
	SCALE 2:1		SHEET	